



PASS

XA60.8





See manual for safety

Negative (-)

AC Mains: Slow Blow
 225-240V 11A/250V
 120V 13A/250V
 100V Requires with the correct type and value fuse.

CAUTION
Risk of electrical shock. Do Not Open.

CE
- AC Mains 50/60 Hz.

Jumper must be used with single-ended input

Positive (+)

See manual for safety

Negative (-)

Signal Gnd

12V External Turn-on

Pass Laboratories, Auburn CA 95602.

PASS



PASS

